


BORE GAUGE



| Code | Range | Indicator | Accuracy | Repeatability |
|------------------|-----------|-----------------------------------------------------------------------------------------|----------|---------------|
| 2828-800A | 400-800mm | dial indicator code 2308-10FA range 10mm, graduation 0.01mm | ±0.025mm | 0.003mm |
| 2128-800A | 400-800mm | digital indicator code 2108-10F range 12.7mm/0.5", resolution 0.002mm/0.0001" | ±0.025mm | 0.003mm |